

Figure 1.





Figure 2.





Figure 3.

## Superalloy Oxidation at 1100°C




Figure 4.




Figure 5.





Figure 6.




Figure 7.




Figure 8.






Figure 9.






Figure 10.




a)




b)

Figure 11.



a)



b)

Figure 12.







Figure 13.



Coated



As-received



Uncoated

Figure 14.




Fig 15.




Fig 16.






Fig 17.




Fig 18.




Figure 19.






Figure 20.



a)



b)

Figure 21.




Figure 22.




Figure 23.